

FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

Date: 12/25/10 Time: 10:00 Location: Powers Loop

Please Circle Appropriate Action: NEW LINE INSTALLATION / LINE REPAIR

NEW LINE INSTALLATION:

Were State approved or AWWA Standards Followed: (YES / NO)
Detailed summary of disinfection procedure used (Use back of page if needed)

COPY

12-28-10
J

Date: Time of Initial Flush: Chlorine Residual after Flush:

Water Supply (WS) Project Number:

FOR LINE REPAIRS:

Interruption of Water Service: YES NO ✓ Number of Customers Affected:

Main Size: 4" PVC Repaired Under Pressure: YES NO

For partially or fully de-watered mains:

Was positive pressure maintained while a trench was opened and area cleaned? (YES / NO)

Time Water Main Valved Off (positive pressure removed): am pm

Nature of Leak or Break:

Were State approved or AWWA Standards Followed: YES NO
Detailed summary of repair procedure used (Use back of page if needed):

Bleached Band 4" x 7 1/2' Full Circle

Was water main contaminated during the repair process? (YES / NO)
Disinfection Procedure / Calculations (Use back of page if needed):

Amount of Time Line Flushed: Minutes Ending Chlorine Residual mg/L

Bacteriological Sample Collected: YES NO Results**
**Attach copy of results to record)

Date: Time Water Main Returned to Service: 20 am pm

Additional Comments:

SD Gpr

