FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

12-27-10 Time: 3Am Location: Powers Loop
Please Circle Appropriate Action: NEW LINE INSTALLATION (INE REPAIR)
NEW LINE INSTALLATION:
Were State approved or AWWA Standards Followed: (YES / NO) De trailed summary of disinfection procedure used (Use back of page if needed)
Date Time of Initial Flush: Chlorine Residual after Flush:
Water Supply (WS) Project Number:
FOR LINE REPAIRS:
Number of Customers Affected 5
Wain Size LI" PVC Repaired Under Pressure: YES NO PROPERTY.
For partially or fully de-watered mains:
Was positive pressure maintained while a trench was opened and area cleaned? (YES)
I me Water Main Valved Off (positive pressure removed): 4Am pm
Crack in Pipe
Were State approved or AWWA Standards Followed: (YES) NO) Detailed summary of repair procedure used (Use back of page if needed):
Ony below pipe & cleaned pipe + material
Disinfection Procedure / Calculations (Use back of page if needed).
Cleaned parts + material with bleech
Amount of Time Line Flushed: Minutes Ending Chlorine Residual mg/L
Bacteriological Sample Collected: YES NO Results**: "Attach copy of results to record)
Date - Time Water Main Returned to Service: 20 am - pm
Additional Comments: