

FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

Date: 9-27-10 Time: 2:30 PM Location: Powers Loop

Please Circle Appropriate Action: NEW LINE INSTALLATION LINE REPAIR

NEW LINE INSTALLATION:

Were State approved or AWWA Standards Followed: (YES / NO)

Detailed summary of disinfection procedure used (Use back of page if needed)

Date Time of Initial Flush:

Chlorine Residual after Flush

Water Supply (WS) Project Number:

FOR LINE REPAIRS:

Interruption of Water Service: YES NO ☒ Number of Customers Affected

Main Size 4" PVC Repaired Under Pressure: YES ☒ NO

For partially or fully de-watered mains:

Was positive pressure maintained while a trench was opened and area cleaned? YES
NO

Time Water Main Valved Off (positive pressure removed): am pm

Nature of Leak or Break:

Split in pipe

Were State approved or AWWA Standards Followed: YES / NO

Detailed summary of repair procedure used (Use back of page if needed):

We cleaned out around pipe & dug below pipe & cleaned with bleach.

Was water main contaminated during the repair process? (YES / NOT)

Disinfection Procedure / Calculations (Use back of page if needed):

Cleaned parts with bleach & put on 4" PVC main.

Amount of Time Line Flushed: Minutes

Ending Chlorine

Residual mg/L

Bacteriological Sample Collected: YES NO

Results**

** Attach copy of results to record)

Date Time Water Main Returned to Service: 20

am pm

Additional Comments:

