

# FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

Date: 2-2-11 Time: 10:00 a.m. Location: Quarry Rd

Please Circle Appropriate Action: NEW LINE INSTALLATION / LINE REPAIR

## NEW LINE INSTALLATION:

Were State approved or AWWA Standards Followed: (YES / NO)

Detailed summary of disinfection procedure used (Use back of page if needed)

**COPY**

2-3-11

Date - Time of Initial Flush: \_\_\_\_\_ Chlorine Residual after Flush: \_\_\_\_\_

Water Supply (WS) Project Number: \_\_\_\_\_

## FOR LINE REPAIRS:

Interruption of Water Service: YES NO ☒ Number of Customers Affected: \_\_\_\_\_

Main Size: 2" PVC Repaired Under Pressure: YES NO

For partially or fully de-watered mains:

Was positive pressure maintained while a trench was opened and area cleaned? (YES / NO) YES

Time Water Main Valved Off (positive pressure removed): \_\_\_\_\_ am / pm

Nature of Leak or Break: Bolts on an old band rotted into

Were State approved or AWWA Standards Followed: (YES / NO)

Detailed summary of repair procedure used (Use back of page if needed):

Replaced old band with new band

Was water main contaminated during the repair process? (YES / NO)

Disinfection Procedure / Calculations (Use back of page if needed): Bleached Band

Amount of Time Line Flushed: \_\_\_\_\_ Minutes Ending Chlorine Residual \_\_\_\_\_ mg/L

Bacteriological Sample Collected: YES NO Results\*\*  
\*\*Attach copy of results to record)

Date - Time Water Main Returned to Service: \_\_\_\_\_ 20 \_\_\_\_\_ am / pm

Additional Comments:

See Photos

Adam - Daniel - Kim - Reed

Copy