

# FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

Date: 8-13-12 Time: 5:00 p.m. Location: Rankin Chapel Rd

Please Circle Appropriate Action: New Line Installation / Line Repair / Service Line

## NEW LINE INSTALLATION:

Were State approved or AWWA Standards Followed: (YES / NO)

Detailed summary of disinfection procedure used (Use back of page if needed):

8-15-12  
J

**COPY**

Chlorine Residual Prior to Initial Flush: \_\_\_\_\_

Date / Time of Initial Flush: \_\_\_\_\_ Length of Time of Initial

Flush: \_\_\_\_\_ Chlorine Residual after Flush: \_\_\_\_\_

Water Supply (WS) Project Number: \_\_\_\_\_

## FOR LINE REPAIRS:

Interruption of Water Service: YES ☒ NO ☐ Number of Customers Affected: 10

Main Size: 4" PVC Repaired Under Pressure: YES ☐ NO ☒

For partially or fully de-watered mains:

Was positive pressure maintained while a trench was opened and area cleaned? (YES / NO) ☒ NO

Time Water Main Valved Off (positive pressure removed): 4 ☒ am / pm

Nature of Leak or Break: Busted water main

Were State approved or AWWA Standards Followed: (YES / NO) ☒ YES

Detailed summary of repair procedure used (Use back of page if needed):

Replaced 40' with Knock-on

Was water main contaminated during the repair process? (YES / NO) ☒ NO Bleached pipe  
Disinfection Procedure / Calculations (Use back of page if needed): and Knock-on

Amount of Time Line Flushed: 1 hr. Minutes  
Residual: \_\_\_\_\_ mg/L

Ending Chlorine 2.20

Bacteriological Sample Collected: YES ☐ NO ☐  
(\*\*Attach copy of results to record)

Results\*\*: \_\_\_\_\_

Date / Time Water Main Returned to Service: 8-13-12 11 ☒ am / pm

Additional Comments: 12" Below pipe was dug

Covered ends after cutting out bad section  
See Photos

COPY