

FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

Date: 12-20-10 Time: 9:30<sup>a.m.</sup> Location: Riggs Chapel & Clifty Crk. Rd

Please Circle Appropriate Action: NEW LINE INSTALLATION / LINE REPAIR

**NEW LINE INSTALLATION:**

Were State approved or AWWA Standards Followed: (YES / NO)

Detailed summary of disinfection procedure used (Use back of page if needed)

COPY

Date: Time of Initial Flush:

Chlorine Residual after Flush

8 12/21/10

Water Supply (WS) Project Number:

**FOR LINE REPAIRS:**

Interruption of Water Service: YES NO Number of Customers Affected

Main Size 4" PVC Repaired Under Pressure: YES NO

For partially or fully de-watered mains:

Was positive pressure maintained while a trench was opened and area cleaned? (YES) NO

Time Water Main Valved Off (positive pressure removed): am pm

Nature of Leak or Break:

split in bottom of pipe

Were State approved or AWWA Standards Followed: (YES) NO

Detailed summary of repair procedure used (Use back of page if needed):

Repaired with band

Was water main contaminated during the repair process? (YES) NO Bleached Bend  
Disinfection Procedure / Calculations (Use back of page if needed):

Amount of Time Line Flushed: Minutes Ending Chlorine  
Residual mg/L

Bacteriological Sample Collected: YES NO Results\*\*

\*\*Attach copy of results to record)

Date: Time Water Main Returned to Service: 20 am pm

Additional Comments: See Photos

12 GPM leak

Adam - Donnie - Bull - Billy - Reed - Tim

