

FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

Date 11-3-09 Time 11Am Location Riggs Chapel Rd.

Please Circle Appropriate Action: New Line Installation / Line Repair / Service Line

NEW LINE INSTALLATION:

Were State approved or AWWA Standards Followed (YES / NO)

Detailed summary of disinfection procedure used (Use back of page if needed)

Chlorine Residual Prior to Initial Flush

Date: Time of Initial Flush Length of Time of Initial
Flush Chlorine Residual after Flush

Water Supply (WS) Project Number

FOR LINE REPAIRS:

Interruption of Water Service: YES ☐ NO ☒ Number of Customers Affected

Main Size: 4" PVC Repaired Under Pressure: YES ☒ NO ☐

For partially or fully de-watered mains

Was positive pressure maintained while a trench was opened and area cleaned? (YES)
NO ☐

Time Water Main Valved Off (positive pressure removed) am pm

Nature of Leak or Break

Crack in PVC Pipe

Were State approved or AWWA Standards Followed (YES) / NO ☐

Detailed summary of repair procedure used (Use back of page if needed)

put bleach on band & cleaned pipe & repaired main.

Was water main contaminated during the repair process? (YES / NO)

Disinfection Procedure / Calculations (Use back of page if needed)

Amount of Time Line Flushed Minutes Ending Chlorine
Residual mg/L

Bacteriological Sample Collected: YES ☐ NO ☐ Results**

**Attach copy of results to record)

Date: Time Water Main Returned to Service am pm

Additional Comments