

# FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

Date: 12-20-10

Time: 11:00 a.m. Location: Riggs Chapel Rd

Please Circle Appropriate Action: NEW LINE INSTALLATION / LINE REPAIR

## NEW LINE INSTALLATION:

Were State approved or AWWA Standards Followed: (YES / NO)

Detailed summary of disinfection procedure used (Use back of page if needed)

COPY

12-21-10  
J

Date: Time of Initial Flush:

Chlorine Residual after Flush

Water Supply (WS) Project Number:

## FOR LINE REPAIRS:

Interruption of Water Service: YES NO ☒ Number of Customers Affected

Main Size 4" PVC

Repaired Under Pressure: YES ☒ NO

For partially or fully de-watered mains:

Was positive pressure maintained while a trench was opened and area cleaned? (YES) ☒ NO

Line Water Main Valved Off (positive pressure removed):

am pm

Nature of Leak or Break:

Split in bottom of 4" main

Were State approved or AWWA Standards Followed: (YES) ☒ NO

Detailed summary of repair procedure used (Use back of page if needed):

Repaired with Band

Was water main contaminated during the repair process? (YES) ☒ NO

Disinfection Procedure / Calculations (Use back of page if needed):

Bleached band

Amount of Time Line Flushed: \_\_\_\_\_ Minutes  
Residual \_\_\_\_\_ mg/L

Ending Chlorine

Bacteriological Sample Collected: YES NO

Results\*\*

\*\*Attach copy of results to record)

Date: Time Water Main Returned to Service: \_\_\_\_\_ 20

am / pm

Additional Comments:

See Photos

10 GPM leak

Adam-Donnie-Bull-Billy-Reed

