

FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

Date: 3-22-11 Time: 10 Am Location: Riggs Chapel Rd.

Please Circle Appropriate Action: New Line Installation (Line Repair) / Service Line

NEW LINE INSTALLATION:

*Taylor Leadbetter, Clark,
Fitzhugh*

Were State approved or AWWA Standards Followed: (YES / NO)

Detailed summary of disinfection procedure used (Use back of page if needed):

COPY

Chlorine Residual Prior to Initial Flush: _____

Date / Time of Initial Flush: _____ Length of Time of Initial

Flush: _____ Chlorine Residual after Flush: _____

Water Supply (WS) Project Number: _____

FOR LINE REPAIRS:

Interruption of Water Service: YES ___ NO ✓ Number of Customers Affected: 0

Main Size: 4" PVC Repaired Under Pressure: YES ✓ NO ___

For partially or fully de-watered mains:

Was positive pressure maintained while a trench was opened and area cleaned? (YES)
NO)

Time Water Main Valved Off (positive pressure removed): _____ am / pm

Nature of Leak or Break:

Crack in Pipe

Were State approved or AWWA Standards Followed: (YES) / NO)

Detailed summary of repair procedure used (Use back of page if needed):

Cleaned parts & material with bleach & dry below + around pipe 16"

Was water main contaminated during the repair process? (YES (NO))

Disinfection Procedure / Calculations (Use back of page if needed):

Cleaned material with bleach

Amount of Time Line Flushed: _____ Minutes

Ending Chlorine

Residual: _____ mg/L

Bacteriological Sample Collected: YES ___ NO ___

Results**: _____

(**Attach copy of results to record)

Date / Time Water Main Returned to Service: _____ am / pm

Additional Comments:

2400