

FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

Date 7-21-11 Time: 11 Am Location: Riggs Chapel Rd.

Please Circle Appropriate Action: New Line Installation / Line Repair / Service Line

NEW LINE INSTALLATION:

Were State approved or AWWA Standards Followed: (YES / NO)
Detailed summary of disinfection procedure used (Use back of page if needed):

Chlorine Residual Prior to Initial Flush: _____
Date / Time of Initial Flush: _____ Length of Time of Initial
Flush: _____ Chlorine Residual after Flush: _____

Water Supply (WS) Project Number: _____

FOR LINE REPAIRS:

Interruption of Water Service: YES ___ NO ✓ Number of Customers Affected 6

Main Size: 4" Pvc Repaired Under Pressure: YES ✓ NO ___

For partially or fully de-watered mains:

Was positive pressure maintained while a trench was opened and area cleaned? (YES)
NO)

Time Water Main Valved Off (positive pressure removed): _____ am / pm

Nature of Leak or Break:

Busted coupling

Were State approved or AWWA Standards Followed: (YES) / NO)
Detailed summary of repair procedure used (Use back of page if needed):

Dug below & around pipe & cleaned material & area

Was water main contaminated during the repair process? (YES) / NO)

Disinfection Procedure / Calculations (Use back of page if needed):

Cleaned parts & material with Bleach

Amount of Time Line Flushed: _____ Minutes Ending Chlorine
Residual: _____ mg/L

Bacteriological Sample Collected: YES ___ NO ___ Results**: _____
(*Attach copy of results to record)

Date / Time Water Main Returned to Service: _____ am / pm

Additional Comments:

5,386

COPY

Taylor
Billy
Bull
Reed
Johnnie

