

FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

Date: 1-24-11 Time: 11Am Location: Ranitan & Tidwell Circle

Please Circle Appropriate Action: NEW LINE INSTALLATION / LINE REPAIR

NEW LINE INSTALLATION:

Taylor, Crabtree, Re
Loggins, Hanna.

Were State approved or AWWA Standards Followed: (YES / NO)

Detailed summary of disinfection procedure used (Use back of page if needed)

1-25-11
8

Date Time of Initial Flush: Chlorine Residual after Flush:

Water Supply (WS) Project Number:

COPY

FOR LINE REPAIRS:

Interruption of Water Service: YES NO ☒ Number of Customers Affected

Main Size: 2" Cast Repaired Under Pressure: YES ☒ NO

For partially or fully de-watered mains:

Was positive pressure maintained while a trench was opened and area cleaned? YES
NO

Time Water Main Valved Off (positive pressure removed): am pm

Nature of Leak or Break:

Crack in pipe at bell

Were State approved or AWWA Standards Followed: YES / NO

Detailed summary of repair procedure used (Use back of page if needed):

Cleaned pipe & dug 18' below pipe & around pipe.

Was water main contaminated during the repair process? (YES / NO)

Disinfection Procedure / Calculations (Use back of page if needed):

Cleaned pipe & material with bleach & installed.

Amount of Time Line Flushed: 45 Minutes Ending Chlorine 2.20
Residual mg/L

Bacteriological Sample Collected: YES NO Results**

** Attach copy of results to record)

Date Time Water Main Returned to Service: 20 am pm

Additional Comments:

COPY