

FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

Date 7-11-10 Time 1:00 p.m. Location South Welden Crown

Please Circle Appropriate Action: New Line Installation Line Repair / Service Line

NEW LINE INSTALLATION:

Were State approved or AWWA Standards Followed: (YES / NO) YES
Detailed summary of disinfection procedure used (Use back of page if needed)

Chlorine Residual Prior to Initial Flush: _____
Date / Time of Initial Flush: _____ Length of Time of Initial
Flush: _____ Chlorine Residual after Flush: _____

Water Supply (WS) Project Number: _____

FOR LINE REPAIRS:

Interruption of Water Service: YES _____ NO YES Number of Customers Affected: _____

Main Size 4" PVC Repaired Under Pressure: YES _____ NO _____

For partially or fully de-watered mains:

Was positive pressure maintained while a trench was opened and area cleaned? (YES / NO) YES

Time Water Main Valved Off (positive pressure removed): _____ am / pm

Nature of Leak or Break: _____

split in top of 4" PVC main

Were State approved or AWWA Standards Followed: (YES / NO) YES
Detailed summary of repair procedure used (Use back of page if needed)

Repaired with Band

Was water main contaminated during the repair process? (YES / NO) NO

Disinfection Procedure / Calculations (Use back of page if needed)
Bleached Ben

Amount of Time Line Flushed: _____ Minutes Ending Chlorine
Residual: _____ mg/L

Bacteriological Sample Collected: YES _____ NO _____ Results** _____
(**Attach copy of results to record)

Date / Time Water Main Returned to Service: _____ am / pm

Additional Comments:

4' x 5' hole

15 sec to raise 6"

