

FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

Date: 9-20-10 Time: 2:30 p.m. Location: S. Welden Crown

Please Circle Appropriate Action: NEW LINE INSTALLATION / LINE REPAIR

NEW LINE INSTALLATION:

Were State approved or AWWA Standards Followed: (YES / NO)

Detailed summary of disinfection procedure used (Use back of page if needed):

Date: Time of Initial Flush:

Chlorine Residual after Flush:

Water Supply (WS) Project Number:

FOR LINE REPAIRS:

Interruption of Water Service: YES NO / Number of Customers Affected

Main Size 2" PVC Repaired Under Pressure: YES / NO

For partially or fully de-watered mains:

Was positive pressure maintained while a trench was opened and area cleaned? (YES / NO)

Time Water Main Valved Off (positive pressure removed): am / pm

Nature of Leak or Break:

split in bottom of 2" PVC main

Were State approved or AWWA Standards Followed: (YES / NO)

Detailed summary of repair procedure used (Use back of page if needed):

Repaired with band

Was water main contaminated during the repair process? (YES / NO)

Disinfection Procedure / Calculations (Use back of page if needed): Bleached Band

Amount of Time Line Flushed: Minutes
Residual mg/L

Ending Chlorine

Bacteriological Sample Collected: YES NO

Results**

**Attach copy of results to record)

Date: Time Water Main Returned to Service: 20

am / pm

Additional Comments:

Been leaking a long time

See Photos

