

FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

Date: 6-10-14 Time: Location: San Sannes Rd.

Please Circle Appropriate Action: New Line Installation / Line Repair / Service Line

NEW LINE INSTALLATION:

COPY

Were State approved or AWWA Standards Followed: (YES / NO)

Detailed summary of disinfection procedure used (Use back of page if needed):

Chlorine Residual Prior to Initial Flush:

Date / Time of Initial Flush: Length of Time of Initial

Flush: Chlorine Residual after Flush:

Water Supply (WS) Project Number:

FOR LINE REPAIRS:

Interruption of Water Service: YES NO Number of Customers Affected: 3

Main Size: 2" PVC Repaired Under Pressure: YES NO

For partially or fully de-watered mains:

Was positive pressure maintained while a trench was opened and area cleaned? (YES)
NO)

Time Water Main Valved Off (positive pressure removed): am / pm

Nature of Leak or Break:

Lightning hit line

Were State approved or AWWA Standards Followed: (YES) / NO)

Detailed summary of repair procedure used (Use back of page if needed):

Dug around & below pipe & cleaned

Was water main contaminated during the repair process? (YES / NO)

Disinfection Procedure / Calculations (Use back of page if needed):

cleaned material with Bleach.

Amount of Time Line Flushed: Minutes

Ending Chlorine

Residual: mg/L

Bacteriological Sample Collected: YES NO

Results**:

(**Attach copy of results to record)

Date / Time Water Main Returned to Service: am / pm

Additional Comments:

COPY