FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR
Date: 12-19-13 Time: Location: Sexton Loop
Please Circle Appropriate Action: New Line Installation / Line Repair / Service Line
NEW LINE INSTALLATION:
Were State approved or AWWA Standards Followed: (YES / NO) Detailed summary of disinfection procedure used (Use back of page if needed):
Chlorine Residual Prior to Initial Flush: Length of Time of Initial Flush: Length of Time of Initial Flush: Chlorine Residual after Flush:
Water Supply (WS) Project Number:
FOR LINE REPAIRS:
Interruption of Water Service: YES NONumber of CustomersAffected:
Main Size: <u>4"pvc</u> Repaired Under Pressure: YES VNO
For partially or fully de-watered mains:
Was positive pressure maintained while a trench was opened and area cleaned? (YES) NO) ¹ Time Water Main Valved Off (positive pressure removed): <u>N/A</u> am / pm
Nature of Leak or Break: Broke Service line replaced service line
Were State approved or AWWA Standards Followed: (YES / NO) Detailed summary of repair procedure used (Use back of page if needed):
Was water main contaminated during the repair process? (YES / NO) Disinfection Procedure / Calculations (Use back of page if needed):
Amount of Time Line Flushed: Minutes Ending Chlorine Residual: mg/L.
Bacteriological Sample Collected: YESNO Results**: (**Attach copy of results to record)
Date / Time Water Main Returned to Service: am / pm
Additional Comments:
Rev 01-21-09

.

V900