

FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

Date: 2-3-11 Time: 7:00 p.m. Location: Snow Hill Rd

Please Circle Appropriate Action: NEW LINE INSTALLATION / LINE REPAIR

NEW LINE INSTALLATION:

Were State approved or AWWA Standards Followed: (YES / NO)

Detailed summary of disinfection procedure used (Use back of page if needed)

COPY

2-4-11
J

Date: Time of Initial Flush:

Chlorine Residual after Flush:

Water Supply (WS) Project Number:

FOR LINE REPAIRS:

Interruption of Water Service: YES NO Number of Customers Affected

Main Size 6" PUC Repaired Under Pressure: YES ✓ NO

For partially or fully de-watered mains:

Was positive pressure maintained while a trench was opened and area cleaned? (YES NO)

Time Water Main Valved Off (positive pressure removed): am pm

Nature of Leak or Break: PUC Knock-on leaking

Were State approved or AWWA Standards Followed: (YES NO)

Detailed summary of repair procedure used (Use back of page if needed):

Replaced both Knock-ons with Bell end of pipe and a band

Was water main contaminated during the repair process? (YES NO)

Disinfection Procedure / Calculations (Use back of page if needed):

Bleached out section of pipe and band

Amount of Time Line Flushed: Minutes
Residual mg/L

Ending Chlorine

Bacteriological Sample Collected: YES NO

Results**

**Attach copy of results to record)

Date: Time Water Main Returned to Service: 20

am pm

Additional Comments:

See Photos

* Positive Pressure coming out of both ends.

Adam-Reed
Daniel-Jeff

Handwritten signature or initials.

17