

# FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

Date: 7-17-13 Time: 11:00 Location: Snow Ln

Please Circle Appropriate Action: New Line Installation / Line Repair / Service Line

## NEW LINE INSTALLATION:

Were State approved or AWWA Standards Followed: (YES / NO)

Detailed summary of disinfection procedure used (Use back of page if needed):

**COPY**

7/22/13 J

Chlorine Residual Prior to Initial Flush: \_\_\_\_\_

Date / Time of Initial Flush: \_\_\_\_\_ Length of Time of Initial

Flush: \_\_\_\_\_ Chlorine Residual after Flush: \_\_\_\_\_

Water Supply (WS) Project Number: \_\_\_\_\_

## FOR LINE REPAIRS:

Interruption of Water Service: YES \_\_\_ NO ✓ Number of Customers Affected: 0

Main Size: 4" POC Repaired Under Pressure: YES ✓ NO \_\_\_

For partially or fully de-watered mains:

Was positive pressure maintained while a trench was opened and area cleaned? (YES / NO) YES

Time Water Main Valved Off (positive pressure removed): \_\_\_\_\_ am / pm

Nature of Leak or Break:

Small split in top of main

Were State approved or AWWA Standards Followed: (YES / NO) YES Repaired with  
Detailed summary of repair procedure used (Use back of page if needed): Band

Was water main contaminated during the repair process? (YES / NO) NO Bleached Band  
Disinfection Procedure / Calculations (Use back of page if needed):

Amount of Time Line Flushed: \_\_\_\_\_ Minutes  
Residual: \_\_\_\_\_ mg/L

Ending Chlorine

Bacteriological Sample Collected: YES \_\_\_ NO \_\_\_  
(\*\*Attach copy of results to record)

Results\*\*: \_\_\_\_\_

Date / Time Water Main Returned to Service: \_\_\_\_\_ am / pm

Additional Comments: See Photos

Adam James T.  
Jimmy Brett

COPY