

Date: 9-23-14 Time: " " Location: Swan Pond & Douglas

Jm, mt, DF, BL, AS, TJ, JH

Detailed summary of disinfection procedure used (Use back of page if needed):

COPY

Flush: Chlorine Residual after Flush:

FOR LINE REPAIRS:

Main Size: 2" Galv. Repaired Under Pressure: YES NO ☒

Was positive pressure maintained while a trench was opened and area cleaned? (YES / NO)

Nature of Leak or Break:

Detailed summary of repair procedure used (Use back of page if needed):

Only around & below line

Disinfection Procedure / Calculations (Use back of page if needed):

Cleaned pipe & material w/ bleach & put in service

Ending Chlorine

Results**:

Date / Time Water Main Returned to Service: _____ am / pm

Rev 01-21-09

