

FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

9-3-10 Time: 10:00 am Location: Swan Pond & Frost Hollow & Honeysuckle

Circle Appropriate Action: NEW LINE INSTALLATION / LINE REPAIR

NEW LINE INSTALLATION:

Were State approved or AWWA Standards Followed: (YES / NO)

Detailed summary of disinfection procedure used (Use back of page if needed)

COPY

Date: Time of Initial Flush:

Chlorine Residual after Flush

Water Supply (WS) Project Number:

FOR LINE REPAIRS:

Interruption of Water Service YES / NO Number of Customers Affected 3

Utility Size: 2" Poly Repaired Under Pressure YES / NO

Was partially or fully de-watered mains:

Was positive pressure maintained while a trench was opened and area cleaned? (YES / NO)

Water Main Valved Off (positive pressure removed): 10:30 am pm

Location of Leak or Break

Fuse at 2" Poly Tee Broken

Were State approved or AWWA Standards Followed: (YES / NO)

Detailed summary of repair procedure used (Use back of page if needed):

Repaired w/ 2" Brass 90 & 2 Transitions, 2 - electric-fuse caps

Was water main contaminated during the repair process? (YES / NO) Bleached Fittings,
Disinfection Procedure / Calculations (Use back of page if needed) Flushed line

Amount of Time Line Flushed:
Residual mg/L

30

Minutes

Ending Chlorine

Bacteriological Sample Collected: YES / NO
*Attach copy of results to record)

Results**

Date: Time Water Main Returned to Service:

20

am - pm

Additional Comments

