

62

FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

Date: 9-22-14 Time: 10:00 AM Location: Voyles Rd.

Please Circle Appropriate Action: New Line Installation / Line Repair / Service Line

COPY

NEW LINE INSTALLATION:

Were State approved or AWWA Standards Followed: (YES / NO)
Detailed summary of disinfection procedure used (Use back of page if needed):

Chlorine Residual Prior to Initial Flush:
Date / Time of Initial Flush: Length of Time of Initial Flush: Chlorine Residual after Flush:

Water Supply (WS) Project Number:

FOR LINE REPAIRS:

Interruption of Water Service: YES NO Number of Customers Affected: 0

Main Size: 2" Repaired Under Pressure: YES NO

For partially or fully de-watered mains:

Was positive pressure maintained while a trench was opened and area cleaned? (YES / NO)

Time Water Main Valved Off (positive pressure removed): am / pm

Nature of Leak or Break: Service line had pin hole in it.

Were State approved or AWWA Standards Followed: (YES / NO)
Detailed summary of repair procedure used (Use back of page if needed):

Replaced service with 3/4" Pex p.p.e.

Was water main contaminated during the repair process? (YES / NO)
Disinfection Procedure / Calculations (Use back of page if needed):

Amount of Time Line Flushed: 1 min Minutes Ending Chlorine Residual: mg/L

Bacteriological Sample Collected: YES NO Results**:

Date / Time Water Main Returned to Service: am / pm

Additional Comments: Taylor, Adam, TJ

Me

CA 99D ...

17 ...

...

...

...

...

...

...

...

...

...

...

...

...

...

...