FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

Date: 8-29-13 Time: 2:00 p.m. Location: Webster Rd

Please Circle Appropriate Action: New Line Installation / Line Repair / Service Line

NEW LINE INSTALLATION:

COPY 8/30/13

Were State approved or AWWA Standards Followed: (YES / NO)
Detailed summary of disinfection procedure used (Use back of page if needed):

Chlorine Residual Prior to Initial Flush:_____
Date / Time of Initial Flush:_____ Length of Time of Initial Flush:_____ Chlorine Residual after Flush:_____

Water Supply (WS) Project Number:_____

FOR LINE REPAIRS:

Interruption of Water Service: YES ✓ NO ___ Number of CustomersAffected: 12

Main Size: 2" PVC Repaired Under Pressure: YES____ NO ✓

For partially or fully de-watered mains:

Was positive pressure maintained while a trench was opened and area cleaned? (YES / NO)
[1]Time Water Main Valved Off (positive pressure removed): _____ am / pm

Nature of Leak or Break: Tied 2" PVC into new 2" Poly

Were State approved or AWWA Standards Followed: (YES / NO) Bleached poly and Flushed for 10 min
Detailed summary of repair procedure used (Use back of page if needed): Tied in with Brass nipple + 3-Bolt Dresser

Was water main contaminated during the repair process? (YES / NO)
Disinfection Procedure / Calculations (Use back of page if needed):

Amount of Time Line Flushed: 30 Minutes Ending Chlorine Residual:____ mg/L

Bacteriological Sample Collected: YES___ NO ___ Results**:_____
(**Attach copy of results to record)

Date / Time Water Main Returned to Service: _____ _____ am / pm

Additional Comments: See Photos
Took PVC off from Galv Feed

Rev 01-21-09

Adam - Taylor - Simmy - T.S. - James T.