

FIELD DATA FOR NEW LINE INSTALLATION OR LINE REPAIR

Date: 1-17-11 Time: 8:30 a.m. Location: Woodsey Rd

Please Circle Appropriate Action: NEW LINE INSTALLATION LINE REPAIR

NEW LINE INSTALLATION:

Were State approved or AWWA Standards Followed: (YES / NO)
Detailed summary of disinfection procedure used (Use back of page if needed)

COPY

Date: Time of Initial Flush: Chlorine Residual after Flush:

Water Supply (WS) Project Number:

FOR LINE REPAIRS:

Interruption of Water Service: YES NO Number of Customers Affected

Main Size: 1" Galv Repaired Under Pressure YES NO

For partially or fully de-watered mains:

Was positive pressure maintained while a trench was opened and area cleaned? YES NO

Time Water Main Valved Off (positive pressure removed): am pm

Nature of Leak or Break: hole in 1" galv main

Were State approved or AWWA Standards Followed: YES NO
Detailed summary of repair procedure used (Use back of page if needed):

Repaired with band

Was water main contaminated during the repair process? YES NO
Disinfection Procedure / Calculations (Use back of page if needed):

Bleached Band

Amount of Time Line Flushed: Minutes Ending Chlorine Residual mg/L

Bacteriological Sample Collected: YES NO Results**
(** Attach copy of results to record)

Date: Time Water Main Returned to Service: 20 am pm

Additional Comments:

See Photos

COPY